
REPARATIE PERFUSOR COMPACT PLUS seria 21807

I.D.: 106600400

Data publicarii 03.12.24 Coduri CPV 50000000-5 50420000-5

Pretul estimativ: 1.242,06 RON - 1.242,06 RON

Descriere: COD DESCRIERE CANTITATE (buc.) PRET LEI / buc FARA TVA VALOARE LEI FARA TVA PIESE
SCHIMB 34502001 LUMP SUM FOR CONSUMABLES (kit material service) 1 50.00 50.00
34522103 HOUSING, UPPER PART PCP (Carcasa partea superioara PCP) 1 567.78 567.78
34522004 POLE CLAMP COMPLETE CP (support prindere CP) 1 269.58 269.58 34522116
DISPLAY BOARD WITH DISPLAY CP (Afisaj LCD CP) 1 354.70 354.70 SERVICII REPARATII
MANOPERA REPARATII +CALIBRARE+TSC 1 0 0 TOTAL DEVIZ FARA TVA = 1242.06 LEI
