
Reparatie aparat KARCHER BD 38/12 pentru sectia UPU-SMURD

I.D.: 53726566

Data publicarii	25.01.21	Coduri CPV	34913000-0 50532000-3
-----------------	----------	------------	-----------------------

Pretul estimativ: 1.451,73 RON - 1.451,73 RON

Descriere: Reparatia contine urmatoarele produse: float replacement - 1 buc, capac carcasa flotor - 1 buc; inel etansare - 1 buc, garnitura - 1 buc, set roata bara de aspirare - 4 buc, set lamele de aspirare - 1 buc, profil anti-stropi - 1 buc, furtun diametru 5 - 1 buc, filtru de greutate - 1 buc, manopera - 4 h
