

---

## reparatii pompe

I.D.: 42023992

---

Data publicarii	22.02.19	Coduri CPV	50000000-5
-----------------	----------	------------	------------

---

Pretul estimativ: 3.750,00 RON - 3.750,00 RON

---

Descriere: rebobinat stator, inlocuit rulmenti, etansare mecanica, inlocuit ulei-Pompa GRUNPHOS 2.2KW/3000T ; remufat cablu, inlocuit etansare mecanica -POMPA SULZER 1.9KW/3000T ; rebobinat stator, inlocuit rulmenti SKF, inlocuit etansare mecanica, inlocuit ulei -POMPA FLIGHT 1.7KW/3000T; demontat montat, rebobinat stator, inloicuit rulmenti SKF, inlocuit etansare mecanica + ulei - POMPA JUNG 1.36KW/3000T

---