

## Pachet accesorii reparatii

I.D.: 44566542

Data publicarii 20.12.19 Coduri CPV 44167000-8

Pretul estimativ: 5.444,23 RON - 5.444,23 RON

Descriere: VALVA POLIETILENA D25\*3/4"FI BUC 10 18.38 NIPLU ZN 3/4" AVIZ SANITAR BUC 20 3.36 SA RAP D200\*1" BUC 1 124.8 ROBINET APA 1" FI PN25 BUC 6 21.5 NIPLU ZN 1" AVIZ SANITAR BUC 2 3.33 NIPLU ZN 1/2" AVIZ SANITAR BUC 2 1.51 CAPAC ZN 1/2" AVIZ SANITAR BUC 20 2.15 DOP RAP D32 BUC 2 3.03 NIPLU ZN 1" AVIZ SANITAR BUC 2 3.33 MUFA ZN 2" AVIZ SANITAR BUC 1 9.24 NIPLU ZN 2" AVIZ SANITAR BUC 1 8.3 VALVA POLIETILENA D32\*1"FI BUC 2 25.41 COLIER REPARATIE INOX DN250(245-255)L BUC 1 327.6 COLIER REPARATIE INOX DN225(240-248)L BUC 1 320.16 COLIER REPARATIE INOX DN200(215-226)L BUC 2 279.45 COLIER REPARATIE INOX DN50(62-70)L BUC 2 122.85 COLIER REPARATIE INOX DN100(105-116)L BUC 2 197.1 COLIER REPARATIE INOX DN100(116-128)L BUC 1 197.1 COLIER REPARATIE INOX DN80(85-92)L BUC 2 133.65 COLIER REPARATIE INOX DN65(78-85)L BUC 1 136.85 ROBINET APA 1 1/2" BUC 5 46.26 ROBINET APA 1 1/4" BUC 5 34.03 ROBINET APA 3/4" BUC 10 10.5 VALVA POLIETILENA D63\*2"FI BUC 3 95.85 VALVA POLIETILENA D32\*1"FI BUC 13 25.41 VALVA POLIETILENA D25\*3/4"FI BUC 10 18.38 NIPLU ZN 3/4" AVIZ SANITAR BUC 10 3.36 NIPLU ZN 1" AVIZ SANITAR BUC 10 3.33 DOP RAP D25 BUC 5 2.39 DOP RAP D32 BUC 5 3.03 MUFA RAP D25 BUC 20 4.08 NIPLU ZN 1 1/2" AVIZ SANITAR BUC 5 6.06 MUFA GEBO 2"FE BUC 3 94.5 MUFA GEBO 2"FI BUC 2 93 MUFA GEBO 1 1/2"FE BUC 3 53.71 MUFA GEBO 1 1/2"FI BUC 2 55.05 SET LEGATURA APOMETRU 3/4 SET 5 10.16 MUFA GEBO 1 1/4"FI BUC 1 52.3