

## Servicii de reparare si de intretinere a autovehiculelor si a echipamentelor conexe HR

I.D.: 106678713

Data publicarii 04.12.24 Coduri CPV 50110000-9

Pretul estimativ: 9.246,72 RON - 9.246,72 RON

Descriere: ORNAMENT ARIPA FATA X1 -298.32 RON LAMP SEMNALIZARE RENAULT X1 -29.41 RON AMORTIZOR SPATE X1- 546.22 RON SENZOR RABATARE CABINA X2- 336.13 RON SURUB SASIU M15X50X1.5 X1- 8.40RON PIULITA M14X12.5 CU GULER X1-1.68 RON SURUB M202X110 X2- 33.61 RON SAIBA PLATA FI14 X6 - 2.52 RON REZERVOR COMBUSTIBIL X1 - 1680.67 RON COLIER PRINDERE REZERVOR X 1 - 42.02 R4ON COLIER INTARIT X 4 - 33.61 RON LUBRIFIANT MULTIFUNCTIONAL X 1 - 12.61 RON SPRAY DEGRIPANT X 1 - 44.54 RON COLIER INTARIT X 2 - 8.40 RON CDUPLA RAPIDA FILETATA X 1 - 29.41 RON REDUCTIE CI FILET X 1 - 5.88 RON FURTUN COMBUSTIBIL X 1 - 15.13 RON CONECTOR FURTUN M 16X1.5 FI 12 X 1 - 16.81 RON SAIBA PLATA FI12 X 8 -3.36 RON PIULITA M12 X 6 - 2.52 RON SURUB M12X140X1.5 X 2 - 13.45 RON SAIBA PLATA FI14 X 4 - 1.68 RON BUSON REZERVOR X 1 - 63.03 RON SURUB M6X60 X 2 - 0.84 RON PIULITA M5 X 4 - 0.34 RON LAMPA LUCAS VO X 1 - 50.42 RON FILTRU USCATOR VO X 1 - 433.28 RON SET SUPORT REZERVOR X 1 - 1.470.59 RON SPRAY CURATAT FRANA X 1 - 25.21 RON WABCOTHYL X 1 - 50.42 RON CUPLA RAPIDA AUTOMATA X 1 - 29.41 RON BUCSA ARC X 2 - 310.92 RON PIULITA M12 X 2 - 0.84 RON SAIBA GROVER FI12 X 1 - 0.42 RON COLIER TR X 15 - 12.61 RON SPRAY CURATAT FRANA X 2 -50.42 RON CUPLA RAPIDA FILETATA FI16 X 1 - 25.21 RON CAPAC DIFERENTIAL VO X1 - 210.08 RON MEMBRAN BLOCAJ DIFERENTIAL X 1 - 84.45 RON BUCSA BARA STABILIZATOR X 2 - 75.63 RON APARATOR NOROI STG FATA X 1 - 294.12 RON APARATOR NOROI INTERIOR STG FATA X 1 - 252.10 RON MANOPERA CF. DEVIZ NR. 886 X 22 - 264