
Reparatie TP50M26/2D

I.D.: 58093788

Data publicarii	18.06.21	Coduri CPV	50511100-1
-----------------	----------	------------	------------

Pretul estimativ: 3.318,70 RON - 3.318,70 RON

Descriere: Reparatia pompei cuprinde urmatoarele piese de schimb: - Inel de uzura - 1buc; - Kit etansare mecanica - 2 buc; - Rulment -1 buc; - Rulment - 1buc; - O-ring 150x3 - 1buc; - O-ring 135x3 - 1buc; - O-ring 46x3 - 2buc; - Ulei - 1litri; Reparatia pompei presupune urmatoarele servicii: - Rebobinare motor; - Demontare/montare/testare.
