
Servicii de reparare masina de spalat rufe LG

I.D.: 55408857

Data publicarii	24.03.21	Coduri CPV	50532000-3
-----------------	----------	------------	------------

Pretul estimativ:	268,00 RON - 268,00 RON
-------------------	-------------------------

Descriere:	EPARATIE MASINA DE SPALAT RUFEE LG, INLOCUIT POMPA EVACUARE APA, ELECTROVALVA LA DGASPC SECTOR 1/CS. STRAULESTI
------------	---
