
Reparatii Sprinter SV40CJS

I.D.: 80448421

Data publicarii	29.03.23	Coduri CPV	50112200-5
-----------------	----------	------------	------------

Pretul estimativ: 14.755,52 RON - 14.755,52 RON

Descriere: Efectuare test scurt Verificare motor Verificare iluminat exterior Inlocuire filtru particule instalatie filtrare gaze arse Inlocuire amortizor de zgomot Demontare/montare recirculare gaze arse Codare calculator Rvacuare amortizor zgomot Colier Inel suspensie Piulita cu autofranare Valva recirculare Adaos de etansare Colier de teava Garnitura flansa Surub cu hexagon exetrior O-ring
