

---

## Serviciul de reparatie motocoasa STIHL

I.D.: 57801769

---

Data publicarii	07.06.21	Coduri CPV	50800000-3
-----------------	----------	------------	------------

---

Pretul estimativ: 800,26 RON - 800,26 RON

---

Descriere: Serviciul de reparatie consta in: - constatarea defectiunilor - identificarea pieselor defecte - inlocuirea pieselor defecte (carcasa ambreiaj, tambur, vaselina, carcasa av, suport, suport, surub, filtru aer, bujie, palpator, masca) - testare/predare

---