
Reparat Pompa JUNG 3,7 KW

I.D.: 42948175

Data publicarii	05.06.19	Coduri CPV	50000000-5 50511000-0
-----------------	----------	------------	-----------------------

Pretul estimativ: 1.646,00 RON - 1.646,00 RON

Descriere: Demontat, montat, rebobinat stator, inlocuit rulmenti SKF, inlocuit etansare mecanica, ulei, rectificat cota rulment in carcasa statorului.
