
Reparatie pentru auto cu nr MAI33553 serie sasiu 2071470

I.D.: 58466053

Data publicarii	29.06.21	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ:	2.486,86 RON - 2.486,86 RON
-------------------	-----------------------------

Descriere:	1. Martor motor aprins in bord (inlocuire senzor egr + conducta egr-) 2.verificare sorb rezervor motorina (nu indica corect)
------------	---
