
Servicii reparatie Volkswagen PH11PMP

I.D.: 39760067

Data publicarii	25.05.18	Coduri CPV	50100000-6
-----------------	----------	------------	------------

Pretul estimativ: 453,30 RON - 453,30 RON

Descriere: Servicii reparatie Volkswagen PH11PMP Schimb placate frana spate: -Placute frana spate demo si montat -Mat.mici -1 set garniture frane et.
