
SERVICII DE REPARATII MERCEDES SB53ECO

I.D.: 80404207

Data publicarii	27.03.23	Coduri CPV	50110000-9
-----------------	----------	------------	------------

Pretul estimativ:	1.270,43 RON - 1.270,43 RON
-------------------	-----------------------------

Descriere: SERVICII DE REPARATIE MERCEDES conf deviz lucrari nr 10805 id 10809 SB53ECO placute frana spate inlocuit injector inlocuit pompa aer
