
Service sisteme securitate si control acces

I.D.: 90833853

| | | | |
|-----------------|----------|------------|------------|
| Data publicarii | 14.12.23 | Coduri CPV | 32552600-3 |
|-----------------|----------|------------|------------|

Pretul estimativ: 1.800,00 RON - 1.800,00 RON

Descriere: Reparatie interfon : post exterior video Hikvision - 1 buc cititor cu tastatura hikvision - 1 buc post interior 7" lcd Hikvision - 1 buc bolt ingropat - 1 buc racord flexibil -2 buc cablu 2x1 - 4 ml
