
Serviciul de reparatie motocoase STIHL

I.D.: 52787412

Data publicarii	18.12.20	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 319,20 RON - 319,20 RON

Descriere: Serviciul de reparatie motocoasa Stihl consta in urmatoarele proceduri: - constatarea defectiunilor - identificarea pieselor defecte - inlocuirea pieselor defecte (cablu acceleratie, bujie, ventil magnetic, filtru aer), curatat cilindru - testare/predare
