
SERVICIU REPARATIE PLACA COMPACTOARE WACKER VP2050

I.D.: 52521479

Data publicarii	11.12.20	Coduri CPV	50531000-6
-----------------	----------	------------	------------

Pretul estimativ: 931,00 RON - 931,00 RON

Descriere: SNUR DEMAROR 1.000 BUJIE 1.000 ULEI SAE30 HONDA 1.000 FILTRU AER HONDA GX 1.000 CABLU ACCELERATIE 1.000 CARBURATOR 1.000 SET RULMENTI VIBRATOR + ULEI (450022001060) 1.000 GARNITURA PARTITIE CARBURATOR 1.000 CURATAT UTILAJ 1.000 MANOPERA 4.000
