
Reparatie Mercedes Benz Sprinter A-10463 UM 01814 Moara Vlasiei

I.D.: 57986451

Data publicarii	14.06.21	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ: 1.394,44 RON - 1.394,44 RON

Descriere: TEST SCURT EFECTUARE, ETANSEITATEA INSTALATIEI DE COMBUSTIBIL VERIFICARE, CONDUCTA RETUR COMBUSTIBIL LA INJECTOR DEMONT, VERIFICARE MOTOR (DUPA TEST SCURT), VERIFICARE PRESIUNI COMBUSTIBIL SI ETANSEITATE, DEMONTARE, MONTARE, A ONSTATARE, CLEMA FIXARE, CONDUCTA RETUR
