

---

## **REPARATIE PERFUSOR COMPACT PLUS seria 14805, 16060, 16059 SI INFUSOMAT COMPACT PLUS seria 4382**

I.D.: 100596288

---

Data publicarii 25.07.24 Coduri CPV 50000000-5 50420000-5

---

Pretul estimativ: 3.298,46 RON - 3.298,46 RON

---

Descriere: • PERFUSOR COMPACT PLUS seria 16060 COD DESCRIERE CANTITATE (buc.) PRET LEI / buc FARA TVA VALOARE LEI FARA TVA PIESE SCHIMB 34502001 LUMP SUM FOR CONSUMABLES (kit material service) 1 50.00 50.00 34522116 DISPLAY BOARD WITH DISPLAY CP (Afisaj LCD CP) 1 354.70 354.70 SERVICII REPARATII MANOPERA REPARATII +CALIBRARE+TSC 1 0 0 • PERFUSOR COMPACT PLUS seria 16059 COD DESCRIERE CANTITATE (buc.) PRET LEI / buc FARA TVA VALOARE LEI FARA TVA PIESE SCHIMB 34502001 LUMP SUM FOR CONSUMABLES (kit material service) 1 50.00 50.00 34522116 DISPLAY BOARD WITH DISPLAY CP (Afisaj LCD CP) 1 354.70 354.70 34774002 SMALL PARTS SET PCP (Kit piese mici pt asamblare PCP) 1 879.00 879.00 SERVICII REPARATII MANOPERA REPARATII +CALIBRARE+TSC 1 0 0 • INFUSOMAT COMPACT PLUS seria 4382 COD DESCRIERE CANTITATE (buc.) PRET LEI / buc FARA TVA VALOARE LEI FARA TVA PIESE SCHIMB 34502001 LUMP SUM FOR CONSUMABLES (kit material service) 1 50.00 50.00 34522202 SENSOR PCB ICPS (PCB senzor presiune ICP) 1 232.88 232.88 34522116 DISPLAY BOARD WITH DISPLAY CP (Afisaj LCD CP) 1 354.70 354.70 SERVICII REPARATII MANOPERA REPARATII +CALIBRARE+TSC 1 0 0 TOTAL DEVIZ FARA TVA = 3298.46 LEI

---