
Reparatie electropompa WILO MHI 206, localitatea Dabaca

I.D.: 46900585

Data publicarii	03.06.20	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ: 1.380,00 RON - 1.380,00 RON

Descriere: Reparatie electropompa WILO MHI 206: - rebobinare motor; - inlocuire presostat; - inlocuire rulmenti motor; - inlocuire etansare mecanica.
