
piese si reparatie buldo Komatsu WB93R5EO

I.D.: 70767532

| | | | |
|-----------------|----------|------------|------------|
| Data publicarii | 29.06.22 | Coduri CPV | 50000000-5 |
|-----------------|----------|------------|------------|

Pretul estimativ: 3.391,00 RON - 3.391,00 RON

Descriere: Servicii de reparare si intretinere - cuprinde: 1 buc filtru ulei motor, 1 buc filtru motorina, 2 buc filtru aer, 15 L ulei motor, 1 buc geam inferior stanga, 2 buc cruci cardan, 2 kituri bride cardan, manopera si deplasare
