

Servicii de reparare Hyundai Tucson cu nr. de inmatriculare CT25API apartinand A.P.I.A.Constanta

I.D.: 44737119

Data publicarii	03.12.19	Coduri CPV	50110000-9
-----------------	----------	------------	------------

Pretul estimativ: 248,27 RON - 248,27 RON

Descriere: SERVICII DE REPARATII CONSTAND IN: -inlocuit placute frana spate INLOCUIT: -placute frana spate 1 buc TOTAL MANOPERA: 84,00 ron TOTAL PIESE: 164,27 ron
