
Reparatie pompa DAB NKP 40-250/230/A/BAQE/15/2 seria 4710, loc Chinteni

I.D.: 71938046

Data publicarii	04.08.22	Coduri CPV	50511100-1 50511000-0
-----------------	----------	------------	-----------------------

Pretul estimativ: 3.201,39 RON - 3.201,39 RON

Descriere: Reparatie pompa DAB NKP 40-250/230/A/BAQE/15/2 seria 4710, loc Chinteni: - rebobinare motor - etanșare mecanică - set rulmenți motor - piese mărunte (adezivi, garnituri, etc.)
