

## Reparatie capitala pompa apa uzata efluent

I.D.: 67506442

Data publicarii 23.03.22 Coduri CPV 50511000-0

Pretul estimativ: 101.843,91 RON - 101.843,91 RON

Descriere: eparatie capitala pompa apa uzata efluent Amacan PB4 700-470/ 806 UTG1  
S.N.:9971639808/000400 M.No 258926 Contine: 1. 18201328 01-26 KIT 2 REPARATIE AMAP  
700 R - 1 x 28,911.08 RON/ BUC 2. 01235099 81-93 RELEU DE PROTECTIE  
BS01.150.1000.1000 - 4 x 127.61 RON/ BUC 3. 19203286 834.02 CABLU ALIMENTARE S1BN8-  
10X1,5 10M - 1 x 4,042.13 RON/ BUC 4. Material marunt (ulei camera etansare, lavete,  
smirghel, vaselina, vopsea, spray curatare, spray lubrifiere, etc) - 1 x 1,412.15 RON/ BUC 5.  
Rebobinare stator motor electric R22 L06-80 P=80 kW aferent electropompa Amacan PB4  
700-470/ 806 UTG1 S.N.:9971639808/000400 M.No 258926 - 1 x 23,200.00 RON/ BUC 6.  
Reconditionare 112 CARCASA PALETELOR STATORICE - 1 x 2,950.00 RON/ BUC 7. Manopera  
asistenta tehnica la punere in functiune (PIF) + Transport (Bucuresti - Braila - Bucuresti) - 1  
x 2,609.72 RON/ BUC  
Reparatie pompa recirculare namol Amacan PA4 700-470/606 UTG1  
S.N.:9971639808/000300 M.No 258445 Contine: 1. 18201328 01-26 KIT 2 REPARATIE AMAP  
700 R - 1 x 28,911.08 RON/ BUC 2. 01548114 59-17 Cheie de tachelaj 17/2000 B 35 - 1 x  
483.31 RON/ BUC 3. 19203286 834.02 CABLU ALIMENTARE S1BN8-F10X1,5 10M - 1 x 4,042.13  
RON/ BUC 4. Material marunt (ulei camera etansare, lavete, smirghel, vaselina, vopsea,  
spray curatare, spray lubrifiere, etc) - 1 x 1,412.15 RON/ BUC 5. Reconditionare 571 ETRIER  
R22/R - 1 x 750.00 RON/ BUC 6. Manopera asistenta tehnica la punere in functiune (PIF) +  
Transport (Bucuresti - Braila - Bucuresti) - 1 x 2,609.72 RON/ BUC