
REPARATII POMPE

I.D.: 46323333

Data
publicarii 13.05.20

Coduri CPV

50511000-0

Pretul
estimativ: 2.696,00 RON - 2.696,00 RON

Descriere: REPARATII POMPA LOWARA 3.2 KW=1459 lei -Rebobinat ; -Ax uzat - confectionat bucsa ; - Schimbat rulmentii ; -Inlocuit presutupe ; REPARATII POMPA LOWARA 1.5 KW =565 lei - Rebobinat ; -Inlocuit presutupe ; -Schimbat rulmentii REPARATII WILO 2.8 KW -Rebobinat ; - Schimbat rulmentii ; -Confectionat presa extras stator ; -Inlocuit presutupe ; -Lucrari mecanice conexe
