
Reparat ambreiaj autoutilitara 3.5t Ford

I.D.: 101412853

Data publicarii	14.08.24	Coduri CPV	50112100-4
-----------------	----------	------------	------------

Termenul limita pentru depunere:	20.08.24 23:30	Pretul estimativ:	6.300,00 RON - 6.300,00 RON
----------------------------------	----------------	-------------------	-----------------------------

Descriere: Reparat ambreiaj autoutilitara 3.5t Ford SM 39 APS, Sectia Tasnad - patineaza ambreiajul. Reparatia cuprinde piese + manopera, dem- rem. cutie de vireze, inlocuit set ambreiaj, inlocuit volant motor, purjare circuit hidraulic ambreiaj, rulment presiune, kit ambreiaj, volanta, etc
