

Inlocuit antena GPS, reparat antena VHF

I.D.: 39986762

Data publicarii	15.10.18	Coduri CPV	50246000-1
-----------------	----------	------------	------------

Pretul estimativ: 817,25 RON - 817,25 RON

Descriere: Demontat antena AIS transponder de la nava ROVINARI 16 si montat la nava ECOEXPRES, efectuat setari.Reparat antena VHF a navei ECOEXPRES.
