
Reparatie motocoasa Stihl FS 120

I.D.: 73911097

Data publicarii	03.10.22	Coduri CPV	98390000-3
-----------------	----------	------------	------------

Pretul estimativ: 545,29 RON - 545,29 RON

Descriere: 1 STH CARBURATOR 4134/28 41341200628 1 BUC x 268.07 2 STH 41341410300 FILTRU DE AER 1 BUC x 35.29 3 STH 00004007011 BUJIE NGK CMR6H 1 BUC x 12.52 4 MANOPERA CONFORM DEVIZ 1 BUC x 87.39 5 GP*11-06012 BUJIE NGK CMR6H PILE COASE STIHL HUSQVARNA 2 BUC x15.13 6 STH 41341410300 FILTRU DE AER 2 BUC x 35.29 7 STH 11411404400 FILTRU AER
