
Reparatii auto BH 15 SCB, VW Crafter

I.D.: 42667624

Data publicarii	08.05.19	Coduri CPV	50112100-4
-----------------	----------	------------	------------

Pretul estimativ: 2.490,63 RON - 2.490,63 RON

Descriere: Manopere: Constatare+Diagnosticare VW Crafter, Demontat-Montat kit de distributie+ pompa de apa, Demontare si inlocuire fulie vibrochen si fulie alternator. Materiale: Kit de distributie, Pompa de apa, File arbore, Filie alternator
