
Reparatie sistem HPLC Shimadzu CARMEN SOCACIU R9453(69)

I.D.: 42955999

Data publicarii	03.06.19	Coduri CPV	50411000-9
-----------------	----------	------------	------------

Pretul estimativ: 2.136,22 RON - 2.136,22 RON

Descriere: Reparatie sistem HPLC Shimadzu. Pretul include: - interventie minima service system HPLC Shimadzu- 1 buc. (1.095,00 RON + TVA) - ferrule, cod 228-46471- 4 buc. (53,90 RON x 4 buc- total 215,60 RON + TVA) - SUS suction filter assy with tubing, cod 228-45708-91- 2 buc. (412,81 RON x 2 buc- total 825,62 RON + TVA) mai putin
