
REPARATII ECHIP IT , MULTIFUNCTIONALE LASER

I.D.: 87543168

Data publicarii	28.09.23	Coduri CPV	30237200-1
-----------------	----------	------------	------------

Pretul estimativ: 955,00 RON - 955,00 RON

Descriere: 1 ROLA PULLEY PICKYUP ASSY 302HN06080 PT FS6525 BUC 1.000 50.00 50.00 2 ROLA DE SEPARATIE KYOCERA 302F909171 FOR FS-3900/4000/2000/4020DN/4200DN 6525 BUC 1.000 75.00 75.00 3 ROLA DE ALIMENTARE KYOCERA 302F906230 FOR FS-2000D/3900DN/4000DN/1100/1300DN6525 BUC 1.000 85.00 85.00 4 MANOPERA REPARATIE ECHIPAMENT CONFORM BON DE SERVICE,FISE INTERVENTIE ORE 2.000 65.00 130.00 1 ROLA DE SEPARATIE KYOCERA 302F909171 FOR FS-3900/4000/2000/4020DN/4200DN 6525 BUC 1.000 75.00 75.00 2 ROLA DE RIDICARE KYOCERA 302F906240 FOR FS-2000D/3900DN/4000DN/1100/1300DN BUC 1.000 65.00 65.00 3 ROLA DE ALIMENTARE KYOCERA 302F906230 FOR FS-2000D/3900DN/4000DN/1100/1300DN6525 BUC 1.000 85.00 85.00 4 Kyocera Clutch Registration (302GR44140) ambreiaj registratie pentru: Kyocera 1. Kyocera Clutch Registration (302GR44140) ambreiaj registratie pentru: Kyocera 1 195 195 2. Kyocera Clutch Registration (302GR44140) ambreiaj registratie pentru: Kyocera 1 65 65 mai putin
