

Serviciul de reparatie spalator Stihl

I.D.: 49083410

Data publicarii	19.08.20	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 445,04 RON - 445,04 RON

Descriere: Serviciul de reparatie consta in urmatoarele proceduri: - constatarea defectiunilor - identificarea pieselor defecte - inlocuirea pieselor defecte (pistol, oring, intrerupator, buton) - testare/predare
