
REPARATIE PERFUSOR SPACE seria 497160

I.D.: 77315534

Data publicarii	13.01.23	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ: 1.363,19 RON - 1.363,19 RON

Descriere: REPARATIE PERFUSOR SPACE seria 497160 DESCRIERE: REPARATIE PERFUSOR SPACE seria 497160 = 1363.19 LEI FTVA P PIESE SCHIMB: - 34502001 Lump Sum for Consumables (kit pentru reparatii) 1buc - 50.00 lei - 34520970 OPERATING UNIT, COMPLETE PSP (panou operare PSP) 1buc - 834.24 lei - 34770025 SYRINGE HOLDER FIXATION (sistem fixare panou frontal) 1buc - 68.55 lei - 34774386 COVER CAP CASE SP (capace suruburi echipament SP) 10buc - 1.04 = 10.40 lei - MANOPERA REPARATII +CALIBRARE+TSC 1buc - 400.00 lei
