

---

## **Reparatie imprimanta HP Laserjet Pro M203 - inlocuire drum unit, schimb fuser si curatare**

I.D.: 70035619

---

Data publicarii	07.06.22	Coduri CPV	50312000-5
-----------------	----------	------------	------------

---

Pretul estimativ:	295,00 RON - 295,00 RON
-------------------	-------------------------

---

Descriere:	Reparatie imprimanta HP Laserjet Pro M203 - inlocuire drum unit, schimb fuser si curatare
------------	---

---