
Reparatie CAT 428F2

I.D.: 99912817

Data publicarii 09.07.24

Coduri CPV

50000000-5

Pretul estimativ: 1.710,00 RON - 1.710,00 RON

Descriere: SENZOR APA IN MOTORINA SWITCH FRANA VERIFICARE SI INLOCUIRE PIESE CAT 428F2
