

Reparatie Mercedes Vito - MAI 18866

I.D.: 66637764

Data publicarii	23.02.22	Coduri CPV	50112100-4
-----------------	----------	------------	------------

Pretul estimativ:	1.413,70 RON - 1.413,70 RON
-------------------	-----------------------------

Descriere: Reparatie Mercedes Vito - inlocuit saiba injector, bujii incandescente, releu bujii, reparat cablaj motor, test clip - piese + manopera
