

Servicii de reparare si intretinere

I.D.: 57875151

Data publicarii	10.06.21	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ: 634,27 RON - 634,27 RON

Descriere: Motocoasa 4 Timpi 24.5cc 0.97 Cp 5.7kg Ebh252u Nota de constatare defecte: Recutor lipsa,aparatoare lipsa,tija uzata,filtru combustibil murdar,filtru aer murdar,conducte combustibil scoapte,etc 1 Ax transmisie ebh252-em2600 DA00000436 1,00 Buc 2 Cap Angrenaj Ebh252u 123833-7 1,00 Buc i3 Cap Cu Fir Ultra Automat Bbc231u/Rbc2110/2510/3101 B-02945 1,00 Buc 4 Protectie Em2651uh 452260-4 1,00 Buc 5 Cover Protector Em2651uh 451097-6 1,00 Buc 6 Hex. Socket Bolt M6x30 Em2651uh 266579-3 2,00 Buc / 1,07 7 Protector Clamp Em2651uh 346073-2 1,00 Buc 8 Protector Extension Em2651uh 135398-7 1,00 Buc 9 Filtru De Benzina Dcs230t Ea3500s 163447-0 1,00 Buc 10 Furtun Alimentare Ebh252u 168472-6 1,00 Buc 11 Element Filtrant Ebh252u 443141-3 1,00 Buc 12 Element Filtrant Ebh252u 443140-5 1,00 Buc 13 Pompa Amorsare Ebh253u 424314-7 1,00 Buc 14 Ulei Honda motor 10W-30 SJ 0.6 litru ULEI HONDA 0.6L 1,00 Buc 15 Revizie motocoasa Demontat/montat reductor+aparatoare+cap cositor+pompa amorsare+filtru combustibil+conducte combustibil+filtru aer+ulei S902 1,00 UM
