
Servicii service roti

I.D.: 86014312

Data publicarii	17.08.23	Coduri CPV	50112100-4 50116500-6
-----------------	----------	------------	-----------------------

Pretul estimativ:	1.638,66 RON - 1.638,66 RON
-------------------	-----------------------------

Descriere:	Servicii service roti: inlocuit camere aer auto (dimensiuni: 750 R 20 - 2 buc; 1000 R 20 - 2 buc; manopera)
------------	---
