
reparat POMPA FLIGHT 2,2KW/1500T

I.D.: 86750586

Data publicarii	04.09.23	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ: 4.730,00 RON - 4.730,00 RON

Descriere: Servicii de reparat POMPA FLIGHT 2,2KW/1500T: demontat montat, rebobinat stator, inlocuit etansari mecanice, inlocuit ulei, inlocuit cablu de alimentare, reconditionat turbina
