

---

## Reparatii a 4 imprimante HP 2055

I.D.: 67968779

---

Data publicarii	06.04.22	Coduri CPV	30232110-8
-----------------	----------	------------	------------

---

Pretul estimativ: 1.420,00 RON - 1.420,00 RON

---

Descriere: Reparatie fuser HP 2055 2 buc 280lei\*2buc=560 lei Reparatie fuser+rola presoare HP2055 380\*1=380 lei Reparatie fuser+film+rola+rezistenta HP 2055 480\*1buc=480 lei

---