

Servicii reparatii hidraulice

I.D.: 102732979

Data publicarii 11.09.24 Coduri CPV 50100000-6

Pretul estimativ: 7.785,00 RON - 7.785,00 RON

Descriere: Servicii reparatii hidraulice: reparat furtun AGR 25 1"+B DN25/2SN (8 buc), reparat furtun DKR 25 1"+B DN25/2SN (6 buc), Furtun clima DN8, Furtun clima DN12, furtun hidr DN16/2SC+DKR 5/8 PO+DKR 3/4 90G+B L=2.20, furtun hidr DN20/2SC+DKR 3/4 PO+DKR 3/4 45G+B L=1.80, reparat furtun AGR 12 1/2+B DN12/2SN (2 buc), furtun hidr DN20/2SC+M 30 PO+DKR 3/4 PO+B L=0.80, furtun hidr DN20/2SC+M 30 45G+DKR 3/4 PO+B L=0.40, niplu 3/4 (2 buc), reparat Racord Rotary, furtun hidr DN12/2SC+ MM PO+M 22 PO+B L=1.80, furtun hidr DN12/2SC+ORS 1" FE+ORF 13/16 PO+B L=2.40 (2 buc), furtun hidr DN16/2SC+M 26 PO+M 26 FE+B L=1.30, furtun hidr DN6/SC+M 10 PO+M 12 90G+B L=1.60, cot M10-12, Cot ORFS 11/16 PO-FE (2 buc), reparat furtun AGR 20 3/4+B DN20/2SN, furtun hidr DN6/2SC+M 16 PO+M 16 90G+B L=2.10 (2 buc), furtun hidr DN16/2SC+ORFS 1" PO+ORFS 1.3/16 PO+B L=1.75 (2 buc), Racord Rotary 3/4 drept, cot 3/4 PO-FE, Niplu M26-3/4, racord Rotary 3/4 90G, DN20/2SC+DKR 3/4 PO+DKR 3/4 90G+B L=1.15 (2 buc), furtun hidr DN16/2SC+ORFS 1" PO+ORFS 1.3/16 PO+B L=1.45, furtun hidr DN12/2SC+ORF 13/16 PO+ORF 13/16 90G+B L=2.30, furtun hidr DN20/2SC+DKR 3/4 PO+DKR 3/4 PO+B L=2.80, reparat furtun DKR 32 1.1/4+B DN32/2SN, reparat furtun AGR 32 1.1/4+B DN32/2SN, furtun hidr DN20/4SH+DKR 3/4 PO+AGR 3/4+B L=2.10 (2 buc), furtun hidr DN10/2SC+M 18 PO+M 18 90G+B L=1.00, Cupla rapida anticipurare PLT 1" mama+tata, furtun hidr DN16/2SC+DKR 5/8 PO+DKR 5/8 PO+B L=0.50, furtun hidr DN12/2SC+DKR 1/2 PO+DKR 1/2 PO+B L=2.00.