

---

## REPARATII AUTO

I.D.: 75985102

---

Data publicarii	04.12.22	Coduri CPV	50112100-4
-----------------	----------	------------	------------

---

Pretul estimativ: 1.689,52 RON - 1.689,52 RON

---

Descriere: Oferta neacceptata in termen: 1.Reparatii auto Dacia Duster PH 47 PCP - Inlocuit bucsi bara stabilizatoare fata, inlocuit termostat, inlocuit lichid racire, inlocuit discuri si placute frana fata, inlocuit conducta apa, test frane, reglat geometrie roti - 1.370,54 lei 2.Reparatii auto Skoda Fabia PH 03 PCP - inlocuit bujii - 318,98 lei

---