
REPARATIE MAKITA DHP 456;REPARATIE INVERTOR SUDURA;REPARATIE TURBOJET KARCHER

I.D.: 42366760

Data publicarii	01.04.19	Coduri CPV	50116100-2
-----------------	----------	------------	------------

Pretul estimativ: 893,00 RON - 893,00 RON

Descriere: REPARATIE MAKITA DHP 456 COMPOZITIE: - PLATOU PERII = 1 BUC x 24.00 RON fara TVA - SET PERII = 1 BUC x 19.00 RON fara TVA - STATOR MAGNETIC = 1 BUC x 60.00 RON fara TVA - MANOPERA = 0.5 ORE x 50.00 RON fara TVA mai putin;REPARATIE INVERTOR SUDURA TELWIN TECHNOLOGY 236 HD COMPOZITIE: - CONDENSATOR PUTERE = 1 BUC x 87.00 RON fara TVA - PROTECTIE SUPRASARCINA = 1 BUC x 56.00 RON fara TVA - MANOPERA = 0.75 ORE x 50.00 RON fara TVA mai putin;REPARATIE TURBOJET KARCHER HDS 5/15 COMPOZITIE: - GARNITURI = 6 BUC x 19.00RON fara TVA - SAIBE = 3 BUC x 4.00 RON fara TVA - SET VALVE = 2 BUC x 102.00 RON fara TVA - VALVA BY PAS = 1 BUC x 217.00RON fara TVA - MANOPERA = 0.75 ORE x 50 RON fara TVA mai putin
