

Servicii Inlocuire senzor defect, reprogramare centrala incendiu Esser

I.D.: 76550316

Data publicarii	16.12.22	Coduri CPV	98390000-3
-----------------	----------	------------	------------

Pretul estimativ: 395,00 RON - 395,00 RON

Descriere: Inlocuire senzor defect, reprogramare centrala incendiu Esser; 1buc x Detector de fum Esser IQ8; 1buc x Soclu pentru detector de fum Esser IQ8; Manopera instalare, reprogramare centrala;
