
Reparatie majora Ureteroscop flexibil Flex XC

I.D.: 66409806

Data publicarii	16.02.22	Coduri CPV	50421000-2
-----------------	----------	------------	------------

Pretul estimativ: 28.531,00 RON - 28.531,00 RON

Descriere: DEFECTIUNI CONSTATATE teaca externa deformata, manson distal spart OPERATIUNI EXECUTATE demontare completa ureteroscop flexibil. Inlocuire teaca externa, inlocuire camasa metalica distala, inlocuire manson distal, inlocuire canal de lucru, verificare CCD, ajustare cabluri de angulare, reglat angulare, efectuat testare finala.
