
REPARATIE IMPRIMANTA HP LASERJET P2015 mkt

I.D.: 72725215

Data publicarii 02.09.22

Coduri CPV

50323200-7

Pretul estimativ: 614,00 RON - 614,00 RON

Descriere: Inlocuire ansamblu fuser, pick-up roller kit, curatare echipament, testare, verificare
