

---

## Pachet piese de schimb

I.D.: 40168498

---

Data publicarii	06.12.18	Coduri CPV	33141625-7
-----------------	----------	------------	------------

---

Pretul estimativ: 514,00 RON - 514,00 RON

---

Descriere: Continut : Pachet piese de schimb necesar pentru reparatia analizorului BC 5380 si Konelab 60i Prime - M801-3100-00234- connection cable - FL 2644 1 x 210 RON - 888822 - lamp connector cable - FL 2757 1 x 304 RON. PREZENTA TINE LOC DE C-DA FERMA.

---