
Reparatie aparat de spalat cu presiune KARCHER HDS 8/18-4 CX

I.D.: 48912544

Data publicarii	14.08.20	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ: 1.794,51 RON - 1.794,51 RON

Descriere: Tip aparat: HDS 8/18-4 CX Serie nr.: fara 1 28840080 Pumpenset 1,00 774,74 774,74 2 55812390 Scaun supapa 1,00 74,53 74,53 3 63623860 O-Ring 5,0 x 1,5 - NBR 80 1,00 2,21 2,21 4 64145590 Filtru material inflamabil 1,00 28,55 28,55 5 26389740 Electrode de aprindere UBS 1,00 45,35 45,35 6 64157610 Duza 1,25 GPH 45 G ES 1,00 80,90 80,90 7 47301410 Filtru complet 1,00 71,83 71,83 8 28800010 Ersatzteilsatz Dichtungen TR 1,00 35,15 35,15 9 62880160 Ulei angrenaj 1L 1,00 67,12 67,12 10 95010190 Timp de lucru 2,50 117,65 294,13 11 95010220 Zona 2 30,1-70 km 1,00 320,00 320,00 Valoare neta RON 1 794,51 +19 % TVA RON 340,96 Valoare totala RON 2 135,46 mai putin
