

---

## Achizitie servicii de reparatie auto

I.D.: 50153884

---

Data publicarii	29.09.20	Coduri CPV	50112000-3
-----------------	----------	------------	------------

---

Pretul estimativ:	1.830,85 RON - 1.830,85 RON
-------------------	-----------------------------

---

Descriere: Reparatie auto constand in inlocuire grupuri spate si rulmentul spate dreapta, la autoturismul Hyundai Tucson TM66TXW, conform devizului nr 11147/23.09.2020

---