

---

## **SERVICII DE REPARATII AUTO MERCEDES VARIO MAI 33113**

I.D.: 42848014

---

Data publicarii	23.05.19	Coduri CPV	50114100-8
-----------------	----------	------------	------------

---

Pretul estimativ: 10.455,46 RON - 10.455,46 RON

---

Descriere: Disc frana 2 buc -672,27 lei etrier stg - 3864,71 lei etrier dr - 3864,71 lei roata polara - 84,03 senzor abs - 462,18 silicon eansare -25,21 curatator fr 2 buc - 33,61 placute frana - 252,1lei senzor uzura 2 buc - 84,03lei lichid frana - 12,605lei manopera - 1100 lei

---