

---

## Servicii de intretinere VW TRANSPORTER

I.D.: 40146178

---

Data publicarii	18.12.18	Coduri CPV	50112200-5
-----------------	----------	------------	------------

---

Pretul estimativ: 1.143,74 RON - 1.143,74 RON

---

Descriere: Servicii de reparare si intretinere autovehicul VW TRANSPORTER ce includ: inlocuire ulei motor, ulei cuplaj Haldex,buson baie ulei,filtru polen,filtru aer,filtru carburant,buson golire Haldex,buson umplere Haldex.

---